REPAIR ORDER - AUDIT COPY FREEMAN MOTOR CO INC 7524 Sw Macadam Ave Portland, OR 97219			Work Phone Home Phone Body	R/O Open Date 1/13/25	R/O Number 6069124/: Receipt No. Original
				R/O Close Date 1/31/25	
			2DR CABRIOLET	Mileage In 69225	Mileage Out 69226
Year 2013	PORSCHE	Model 911	License Number	Chris Willia	Advisor
	e Identification Number	Color	Account No.	Delivery Date	In-Service Date
WPOCB2A90DS156159 WHITE INVENTORY: SEP6159				1/29/25	
#1 - FSI: FREEMAN SERVICE INSPECTION -INTERNAL **IF CHECK ENGINE LIGHT IS ON, PULL CODES AND CHECK FOR SERVICE BULLETINS** Work performed by Tech 647/ * 1.80hrs 108.0 PERFORMED FSI					
#2 - DEQI: CHECK VEHICLE FOR DEQ COMPLIANCE Work performed by Tech 647/ 0.00hrs @ PERFORMED DEQ					I
#3 - ILOF: INTERNAL LUBE, OIL AND FILTER CHANGE Work performed by Tech 647/ * 0.70hrs 42.00 S84694: OIL FILTER 1@20.55 S5W40: 5W40 FULLSYNTHETIC 8100 XCLEAN 8@8.95 PERFORMED LOF					
Wo	- DETSALEM: INTERNAL DETAIL - SALEM STORE Work performed by Tech 982/ * 5.00hrs PERFORMED INTERNAL DETAIL				I
Wo: S01 SZI	stomer Reports: REPLACED AT To the performed by Top PB-121-959 : COOLEREXG40 : G40 PINTEREXG40 CCV	HIS VISIT ech 647/ * ANT CONTROL VAL	5.40hrs	324.00 68 57.68	
Work cook head correction on slice no	6 * Customer Reports: [OTHER]: PRESSURE TEST COOLING SYSTEM LOOK FOR LEA KS Work performed by Tech 647/ * 1.50hrs 90 coolant level fine, small amount of moisture on heater control valve cooling system diag complete. pressure tested and let sit while i was on lunch. after about 1 hour i can see very slight seepage coming from coolant control valve. no active drips formed. very slight moisture coming from seam in coolant control valve. this				
LABOR		INTERNAL SE	RVICE CONT. WARRANT	CUSTOMER PAY	COST
PARTS					
DEDUCTIBLE					
SUBLET SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
ISCOUNTS					