12/11/24, 1:23 PM image.png

## Multi-Point Inspection Form

**RO**# 6068027 **INVENTORY: PNB9986** 

VIN WBX73EF03R5Y89986

Advisor Irma Merrow Technician Aaron Ostapenko Created On 12/11/2024

Checked and OK at this time	May Require Future Attention	Requires immediate attention
Interior / Exterior		Under Hood
Bulbs and Lights  Windshield Wipers / Windshield Washer Spray / Wiper Operation / Wiper Blades Wiper Arms / Including Rear (if applicable Windshield Condition (inspect for Cracks, Chips, or Pitting)  Upholstery / Carpet / Floor Mats / Mirrors Glass  Emergency Brake Adjustment  Horn Operation  Fuel Tank Cap Gasket  Clutch Operation (if equipped)  Air Conditioning Filter (if equipped)	Stee Eng Driv Eng Coo Con Rad (if e	d Levels: Oil / Coolant / Battery / Power ering / Brake Fluid / Washer ine Air Filter / Belts (condition and adjustment) ine Coolant Protection bling System Hoses / Heater Hoses / Air additioning Hoses and Connections diator Core / Air Conditioning Condenser equipped)  Battery Performance tery Terminals / Cables / Mountings eck Condition of Battery (Storage Capacity t if Applicable)
Cabin/HEPA Filter (if equipped) Engine Air Filter Wiper Blades		ead Depth (measured in 1/32")
Under Vehicle		
Shock Absorbers / Suspension Steering Gear Box / Linkage and Boots / B Joints / Dust Covers Muffler / Exhaust Pipes / Mountings	Ball LF &	<u>5</u> Z
Engine Oil and/or Fluid Leaks  Drive Shaft Boots / Constant Velocity Boot U-joints / Transmission Linkage (if equipy Transmission / Differential / Transfer Cas (Check Fluid Level, Fluid Condition and Fl Leaks)  Fuel Lines and Connections / Fuel Tank B / Fuel Tank Vapor Vent System Hoses  Inspect Nuts and Bolts on Body Chassis	ots / ped) ie uid LR	<u>8</u> 9