

# Multi-Point Inspection Form

**RO# 6068431**  
**INVENTORY: PNV0785**  
**VIN YV4H60CF8R1250785**


**Advisor Irma Merrow**  
**Technician Michael Harry**  
 Created On 12/11/2024

Checked and OK at this time

May Require Future Attention

Requires immediate attention

| Interior / Exterior                 |  |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Bulbs and Lights   |
| <input checked="" type="checkbox"/> | Windshield Wipers / Windshield Washer Spray / Wiper Operation / Wiper Blades / Wiper Arms / Including Rear (if applicable) |
| <input checked="" type="checkbox"/> | Windshield Condition (inspect for Cracks, Chips, or Pitting)   |
| <input checked="" type="checkbox"/> | Upholstery / Carpet / Floor Mats / Mirrors / Glass   |
| <input checked="" type="checkbox"/> | Emergency Brake Adjustment   |
| <input checked="" type="checkbox"/> | Horn Operation   |
| <input checked="" type="checkbox"/> | Fuel Tank Cap Gasket   |
| <input checked="" type="checkbox"/> | Clutch Operation (if equipped)   |
| <input checked="" type="checkbox"/> | Air Conditioning Filter (if equipped)  |
| <input checked="" type="checkbox"/> | Cabin/HEPA Filter (if equipped)  |
| <input checked="" type="checkbox"/> | Engine Air Filter  |
| <input checked="" type="checkbox"/> | Wiper Blades   |
| Under Vehicle                       |  |
| <input checked="" type="checkbox"/> | Shock Absorbers / Suspension   |
| <input checked="" type="checkbox"/> | Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers  |
| <input checked="" type="checkbox"/> | Muffler / Exhaust Pipes / Mountings  |
| <input checked="" type="checkbox"/> | Engine Oil and/or Fluid Leaks  |
| <input checked="" type="checkbox"/> | Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)                                |
| <input checked="" type="checkbox"/> | Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)                           |
| <input checked="" type="checkbox"/> | Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses  |
| <input checked="" type="checkbox"/> | Inspect Nuts and Bolts on Body Chassis   |

| Under Hood  |   |
|---|---|
| <input checked="" type="checkbox"/>   | Fluid Levels: Oil / Coolant / Battery / Power Steering / Brake Fluid / Washer |
| <input checked="" type="checkbox"/>   | Engine Air Filter   |
| <input checked="" type="checkbox"/>   | Drive Belts (condition and adjustment)  |
| <input checked="" type="checkbox"/>   | Engine Coolant Protection   |
| <input checked="" type="checkbox"/>   | Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections  |
| <input checked="" type="checkbox"/>   | Radiator Core / Air Conditioning Condenser (if equipped)                      |
| Battery Performance   |   |
| <input checked="" type="checkbox"/>   | Battery Terminals / Cables / Mountings  |
| <input checked="" type="checkbox"/>   | Check Condition of Battery (Storage Capacity Test if Applicable)              |
| Tread Depth (measured in 1/32")   |   |
|  |   |
| <input checked="" type="checkbox"/>   | LF <u>9</u>   |
| <input checked="" type="checkbox"/>   | RF <u>6</u>   |
| <input checked="" type="checkbox"/>   | LR <u>9</u>   |
| <input type="checkbox"/>  | RR <u>5</u>   |
| Abnormal Wear Pattern of Tires  |   |
| <input type="checkbox"/>  | LF  |
| <input type="checkbox"/>  | RF  |
| <input type="checkbox"/>  | LR  |
| <input type="checkbox"/>  | RR  |
| Check Brake Linings (measured in millimeters)                                       |   |
| <input checked="" type="checkbox"/>   | LF <u>11</u>  |
| <input checked="" type="checkbox"/>   | RF <u>11</u>  |
| <input checked="" type="checkbox"/>   | LR <u>10</u>  |
| <input checked="" type="checkbox"/>   | RR <u>10</u>  |