

CUSTOMER #: 32998

208261



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400

PAGE 1

www.kunibmw.com

HOME: [REDACTED] CONT: [REDACTED]
BUS: [REDACTED] CELL: [REDACTED]

SERVICE ADVISOR: 3042863 DAVID STOUT

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		15166/15167	TP107

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	19:00 07MAR19			CASH	07MAR19

R.O. OPENED	READY	OPTIONS:	SOLD-STK:PHV786537A DLR:36021
15:51 06MAR19	16:51 07MAR19	ENG:3.0L DOHC Turbo	
		TRN:2MK M DOUBLE-CLUTCH TRANSMISSION	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER HAS A NEW CLUSTER HE WOULD LIKE INSTALLED AND CODED TO THE CAR. PART ON RIGHT FRONT SEAT. SAVE OLD PART FOR CUSTOMER AND PLACE IN BOX.I/A

CAUSE: NO CODING RETROFIT AVAILABLE.
33 ELECTRICAL (CHASSIS)
999 CB 0.00 0.00

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00
15167 NO CODING RETROFIT AVAILABLE. CONNECTED VEHICLE FOR PROGRAMMING. FOUND NO CONVERSION CODING AVAILABLE FOR LCI INSTRUMENT CLUSTER. UNABLE TO PERFORM RETROFIT AT THIS TIME. PER CUSTOMER REQUEST, INSTALLED PROVIDED LCI INSTRUMENT CLUSTER WITHOUT CODING. NOTE THAT INSTRUMENT CLUSTER FUNCTIONS ARE INOPERATIVE AND INACCURATE. MULTIPLE ERRONEOUS MESSAGES DISPLAYED ON CID DUE TO LACK OF CODING.

B COURTESY INSPECTION
CAUSE: PERFORM MPI INSPECTION
02BMZ COURTESY INSPECTION
999 INSP

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00 (N/C)

EST: 368.00 06MAR19 15:51 SA: 3042863

COMPANY NAME BMW MAINTENANCE
COMPANY PHONE
POLICY NUMBER TBD.INS3
POLICY TERM 36
EFFECTIVE DATE 26 JAN 2018
DEDUCTIBLE 0.00
MILEAGE LIMIT
BEGIN MILES 9655
END MILES
COMPONENTS

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	DESCRIPTION	TOTALS
	LABOR AMOUNT	
	PARTS AMOUNT	
	GAS, OIL, LUBE	
	SUBLET AMOUNT	
	MISC. CHARGES *	
	TOTAL CHARGES	
	LESS INSURANCE	
	SALES TAX	
	PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 32998

208261



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400

PAGE 2

www.kunibmw.com

HOME: [REDACTED]
BUS: [REDACTED]

SERVICE ADVISOR: 3042863 DAVID STOUT

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		15166/15167	TP107	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	19:00 07MAR19			CASH	07MAR19
R.O. OPENED	READY	OPTIONS:					
15:51 06MAR19	16:51 07MAR19	SOLD-STK:PHV786537A DLR:36021 ENG:3.0L DOHC Turbo TRN:2MK M DOUBLE-CLUTCH TRANSMISSION					
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 32998

96637



INVOICE

3725 SW Cedar Hills Blvd., Beaverton, OR 97005
(503) 643-1543
www.kuniautocenter.com

PAGE 1

SERVICE ADVISOR: 3042329 ISIAIAH MARTIN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		15283/15283	TG519	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DL	19AUG16	29SEP2020	17:00 25MAR19		60.00	KCC	29MAR19

R.O. OPENED READY OPTIONS: SOLD-STK:PHV786537A DLR:36021
 ENG:3.0L DOHC Turbo
 12:29 25MAR19 10:47 29MAR19 TRN:2MK M DOUBLE-CLUTCH TRANSMISSION

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A REPAIR PER ESTIMATE
 RPE REPAIR PER ESTIMATE
 3042342 CCBI 445.20 445.20
 BMAT BODY MATERIALS 9.00 9.00
 PARTS: 0.00 LABOR: 445.20 OTHER: 9.00 TOTAL LINE A: 454.20

B PAINT PER ESTIMATE
 PPE PAINT PER ESTIMATE
 3042338 CCBI 243.80 243.80
 BPAINT PAINT SUPPLIES 135.30 135.30
 PPE PAINT PER ESTIMATE
 777 CCBI 26.50 26.50
 BPAINT PAINT SUPPLIES 0.00 0.00
 PARTS: 0.00 LABOR: 270.30 OTHER: 135.30 TOTAL LINE B: 405.60

C You consent to receiving texts from us at the number you have provided. You agree that we may contact you regarding customer service updates or offers via text. If you do not agree, you may provide a landline number. You may opt out at any time.
 TEXT You consent to receiving texts from us at the number you have provided. You agree that we may contact you regarding customer service updates or offers via text. If you do not agree, you may provide a landline number. You may opt out at any time.
 999 CCBI 0.00 0.00
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

COMPANY NAME BMW MAINTENANCE
 COMPANY PHONE
 POLICY NUMBER TBD.INS3
 POLICY TERM 36
 EFFECTIVE DATE 26 JAN 2018

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
DATE	CUSTOMER SIGNATURE
	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE
PLEASE PAY THIS AMOUNT	

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

CUSTOMER #: 32998

96637



INVOICE

3725 SW Cedar Hills Blvd., Beaverton, OR 97005
(503) 643-1543
www.kuniautocenter.com

PAGE 2

SERVICE ADVISOR: 3042329 ISATAH MARTIN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
LONGBRACH	17	BMW M2	WBS1H9C53HV786537		15283/15283	TG519	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	17:00 25MAR19		60.00	KCC	29MAR19

R.O. OPENED	READY	OPTIONS:	SOLD-STK:PHV786537A DLR:36021
12:29 25MAR19	10:47 29MAR19	ENG:3.0L DOHC Turbo	
TRN:2MK M DOUBLE-CLUTCH TRANSMISSION			
LINE OPCODE	TECH TYPE	HOURS	LIST NET TOTAL
DEDUCTIBLE		0.00	
MILEAGE LIMIT			
BEGIN MILES		9655	
END MILES			
COMPONENTS			



www.kunicollisioncenter.com

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	715.50
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	144.30
TOTAL CHARGES	859.80
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	859.80

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 32998

96692



INVOICE

3725 SW Cedar Hills Blvd., Beaverton, OR 97005
(503) 643-1543
www.kuniautocenter.com

PAGE 1

SERVICE ADVISOR: 3041787 IAN PETERSON

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		15283/15283	

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	17:00 29MAR19		60.00	KCC	29MAR19

R.O. OPENED	READY	OPTIONS:	SOLD-STK:PHV786537A DLR:36021				
		ENG:	3.0L DOHC Turbo				
10:03 29MAR19	10:04 29MAR19	TRN:	2MK M DOUBLE-CLUTCH TRANSMISSION				
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

A CHECK FAULT CODES							
MPE CHECK FAULT CODES							
3042342 CCBB							
PARTS:	0.00	LABOR:	130.00	OTHER:	0.00	TOTAL LINE A:	130.00

COMPANY NAME BMW MAINTENANCE
 COMPANY PHONE
 POLICY NUMBER TBD.INS3
 POLICY TERM 36
 EFFECTIVE DATE 26 JAN 2018
 DEDUCTIBLE 0.00
 MILEAGE LIMIT
 BEGIN MILES 9655
 END MILES
 COMPONENTS



www.kunicollisioncenter.com

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	DESCRIPTION	TOTALS
		LABOR AMOUNT	130.00
		PARTS AMOUNT	0.00
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES *	0.00
		TOTAL CHARGES	130.00
		LESS INSURANCE	0.00
		SALES TAX	0.00
		DATE	CUSTOMER SIGNATURE
			130.00



KUNI COLLISION CENTER

Workfile ID: 6c900f29
Federal ID: 21-0610247

AS A BMW AND LEXUS CERTIFIED REPAIR CENTER, WE ONLY USE NEW OEM PARTS. WE DO NOT USE AFTERMARKET, LKQ OR RECONDITIONED PARTS.

3725 SW CEDAR HILLS BLVD, P.O. BOX 4810,
BEAVERTON, OR 97005
Phone: (503) 372-7570
FAX: (888) 633-5670

Supplement of Record 1 with Summary

RO Number: 96637

Written By: Isaiah Martin, 3/28/2019 10:30:19 AM

Insured:	IRISH, BRIAN	Policy #:		Claim #:	0154300621001
Type of Loss:	Collision	Date of Loss:	3/24/2019 12:00 PM	Days to Repair:	3
Point of Impact:	06 Rear				

Owner:

Inspection Location:

Insurance Company:

KUNI COLLISION CENTER
3725 SW CEDAR HILLS BLVD
P.O. BOX 4810
BEAVERTON, OR 97005
Repair Facility
(503) 372-7570 Business

USAA

VEHICLE

2017 BMW M2 2D CPE 6-3.0L Turbocharged Gasoline Gasoline Direct Injection BLUE / C16

VIN:	WBS1H9C53HV786537	Interior Color:		Mileage In:	15,283	Vehicle Out:	3/29/2019
License:	GW00745	Exterior Color:	BLUE / C16	Mileage Out:			
State:	OR	Production Date:	8/2016	Condition:		Job #:	

TRANSMISSION

6 Speed Transmission

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Memory Package

DECOR

Dual Mirrors

CONVENIENCE

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Climate Control
Navigation System
Home Link

FM Radio

Stereo
Search/Seek
CD Player
Auxiliary Audio Connection
Premium Radio
Satellite Radio
Equalizer

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags

Communications System

Hands Free Device

SEATS

Leather Seats
Heated Seats

WHEELS

Aluminum/Alloy Wheels

PAINT

Clear Coat Paint

OTHER

Traction Control
Stability Control
Rear Spoiler
Signal Integrated Mirrors

Supplement of Record 1 with Summary

RO Number: 96637

2017 BMW M2 2D CPE 6-3.0L Turbocharged Gasoline Gasoline Direct Injection BLUE / C16

Tinted Glass
Console/Storage

RADIO
AM Radio

Head/Curtain Air Bags
Positraction

Xenon Headlamps
Power Trunk/Gate Release

Supplement of Record 1 with Summary

RO Number: 96637

2017 BMW M2 2D CPE 6-3.0L Turbocharged Gasoline Gasoline Direct Injection BLUE / C16

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1		REAR LAMPS					
2	S01 R&I	RT Tail lamp				0.4	
3	S01 R&I	LT Tail lamp				0.4	
4		REAR BUMPER					
5		O/H bumper assy				3.1	
6	R&I	R&I bumper cover				Incl.	
7	* S01 Rpr	Bumper cover				<u>4.5</u>	2.6
8		Add for Clear Coat					1.0
9	R&I	Valance panel				Incl.	
10	R&I	RT Reflector				Incl.	
11	R&I	LT Reflector				Incl.	
12		MISCELLANEOUS OPERATIONS					
13	# S01	Tint		1		0.5	
14	# S01	De-Nib and Polish		1		0.5	
15	* Repl	<u>Flex Additives</u>		1	<u>6.00</u>	<u>0.0</u>	
16	#	Hazardous Waste Removal		1	3.00 X		
17	# S01 Refn	Prime, Block and Fill					0.5
18	# S01 Subi	Clear Fault Codes		1	130.00 X		
SUBTOTALS					139.00	9.4	4.1

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			6.00
Body Labor	9.4 hrs @	\$ 53.00 /hr	498.20
Paint Labor	4.1 hrs @	\$ 53.00 /hr	217.30
Paint Supplies	4.1 hrs @	\$ 33.00 /hr	135.30
Miscellaneous			133.00
Subtotal			989.80
Grand Total			989.80
Deductible			500.00
CUSTOMER PAY			500.00
INSURANCE PAY			489.80

Supplement of Record 1 with Summary

RO Number: 96637

2017 BMW M2 2D CPE 6-3.0L Turbocharged Gasoline Gasoline Direct Injection BLUE / C16

SUPPLEMENT SUMMARY

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
Changed Items							
3	*	Rpr Bumper cover				-3.0	-2.6
7	*	S01 Rpr Bumper cover				4.5	2.6
Added Items							
1	REAR LAMPS						
2	S01	R&I RT Tail lamp				0.4	
3	S01	R&I LT Tail lamp				0.4	
13	#	S01 Tint		1		0.5	
14	#	S01 De-Nib and Polish		1		0.5	
17	#	S01 Refn Prime, Block and Fill					0.5
18	#	S01 Subl Clear Fault Codes		1	130.00 X		
SUBTOTALS					130.00	3.3	0.5

TOTALS SUMMARY

Category	Basis	Rate	Cost \$
Parts			0.00
Body Labor	3.3 hrs @	\$ 53.00 /hr	174.90
Paint Labor	0.5 hrs @	\$ 53.00 /hr	26.50
Paint Supplies	0.5 hrs @	\$ 33.00 /hr	16.50
Miscellaneous			130.00
Subtotal			347.90
Total Supplement Amount			347.90
NET COST OF SUPPLEMENT			347.90

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

Estimate	641.90	Isaiah Martin
Supplement S01	347.90	Isaiah Martin
Job Total:	\$ 989.80	
CUSTOMER PAY:	\$ 500.00	
INSURANCE PAY:	\$ 489.80	

ORS-746.280 DESIGNATION OF PARTICULAR MOTOR VEHICLE REPAIR SHOP BY INSURER PROHIBITED. AN INSURER SHALL NOT REQUIRE THAT A PARTICULAR PERSON MAKE REPAIRS TO THE INSURED'S VEHICLE AS A CONDITION FOR RECOVERY BY THE INSURED UNDER A MOTOR VEHICLE LIABILITY INSURED POLICY (1977 C.785.21.)

Supplement of Record 1 with Summary

RO Number: 96637

2017 BMW M2 2D CPE 6-3.0L Turbocharged Gasoline Gasoline Direct Injection BLUE / C16

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERE1928, CCC Data Date 03/15/2019, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2019 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category.
X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category.
M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Align.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel.
CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel.
HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non
Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace.
R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel.
Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway
Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

<uni BMW

10999 SW CANYON RD

Beaverton Oregon 97005

503-748-5400

Sale

Date: 03/29/2019 2:20 P

Merchant ID: 12720433

Terminal ID: 00000001

Invoice No.: 209623_KBM...

Amount: \$641.90

Card Number: *****8714

Response Msg: Approved

Auth Code: 08780D

Auth Mode: Issuer

Application Name: Visa Credit

Processed as: VISA

Entry Method: Chip Read

Trace No.: 589088768337...

Reference No.: 1519203277

Match AVS: Not Present

Match ZIP: Not Present

Match CVV: Not Present

Chip Card AID: A0000000031...

TVR: 8000008000

IAD: 06010A03A02...

TSI: 6800

ARC: 00

Client ID: 32998

User ID: ck10_dms

Cardholder Signature



CUSTOMER #: 32998

702623



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 1

SERVICE ADVISOR: 3042863 DAVID STOUT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG. Row 1: LONGBRACH-17 BMW M2, WBS1H9C53HV786537, 19373/19375, TP151. Row 2: DEL DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 3: 30SEP16 IS, 30SEP16 DD, 19AUG16, 29SEP2020, 16:00, 06AUG19, CASH, 06AUG19.

Table with columns: R.O. OPENED, READY, OPTIONS, SOLD-STK, PHV, DLR, ENG, TRN. Row 1: 16:56, 05AUG19, 15:13, 06AUG19, SOLD-STK:PHV786537A, DLR:36021, ENG:3.0L DOHC Turbo, TRN:2MK M DOUBLE-CLUTCH TRANSMISSION.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Row 1: A BRAKE FLUID DUE, CAUSE: BRAKE FLUSH, 10 BRAKE SYSTEMS, 3042976 WBM, 3 81-22-0-142-156 BRAKE FLUID:832560, PARTS: 0.00, LABOR: 0.00, OTHER: 0.00, TOTAL LINE A: 0.00.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Row 1: B MULTI POINT INSPECTION, 02BMZ DEFAULT, 3042976 INSP, PARTS: 0.00, LABOR: 0.00, OTHER: 0.00, TOTAL LINE B: 0.00.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Row 1: C STANDARD SCOPE, CAUSE: STANDARD SCOPE, 01 MENU SERVICES, 3042976 WBM, PARTS: 0.00, LABOR: 0.00, OTHER: 0.00, TOTAL LINE C: 0.00.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Row 1: D OIL CHANGE COMING DUE BASED ON 60 DAY WINDOW, CAUSE: OIL SERVICE, 06BMZ CAR NEEDS REGULAR LUBE OIL AND FILTER, 3042976 WBM, 1 11-42-7-854-445 SET OIL-FILTER ELEMENT:114010, 65 83-21-2-450-384 BMW GROUP LL-01 FE 0W-30, BUL:832511, 1 83-19-2-221-702 BMW WINDSHIELD WASHER FLUID:831510, PARTS: 0.00, LABOR: 0.00, OTHER: 0.00, TOTAL LINE D: 0.00.

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

Table with columns: DESCRIPTION, TOTALS. Rows: LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES *, TOTAL CHARGES, LESS INSURANCE, SALES TAX, PLEASE PAY THIS AMOUNT.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 32998

702623



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 2

SERVICE ADVISOR: 3042863 DAVID STOUT

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG. Row 1: LONGBRACH-17, BMW M2, WBS1H9C53HV786537, 19373/19375, TP151. Row 2: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO. NO., RATE, PAYMENT, INV. DATE. Row 3: 30SEP16 IS, 30SEP16 DD, 19AUG16, 29SEP2020, 16:00, 06AUG19, CASH, 06AUG19.

R.O. OPENED READY OPTIONS: SOLD-STK:PHV786537A DLR:36021
ENG:3.0L DOHC Turbo
TRN:2MK M DOUBLE-CLUTCH TRANSMISSION

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

E AIR FILTER COMIG DUE BASED ON 60 DAY WINDOW
CAUSE: AIR FILTER
03 GENERAL MAINTENANCE
3042976 WBM (N/C)
1 13-71-7-602-643 AIR FILTER ELEMENT:137012 (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00
19375 AIR FILTER REPLACED AIR FILTER

F SPARK PLUGS COMING DU BASED ON 60 DAY WINDOW
CAUSE: SPARK PLUGS DUE
04 IGNITIONS SYSTEMS
3042976 WBM (N/C)
6 12-12-0-039-634 SPARK PLUG, HIGH (N/C)
POWER:121031
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE F: 0.00
19375 SPARK PLUGS DUE REPLACED SPARK PLUGS

G 01 MENU SERVICES
3042976 CB 0.00 0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G: 0.00

EST: 1,173.81 05AUG19 16:56 SA: 3042863

COMPANY NAME BMW MAINTENANCE
COMPANY PHONE
POLICY NUMBER TBD.INS3
POLICY TERM 36
EFFECTIVE DATE 26 JAN 2018
DEDUCTIBLE 0.00
MILEAGE LIMIT
BEGIN MILES 9655

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

Table with columns: DESCRIPTION, TOTALS. Rows: LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES *, TOTAL CHARGES, LESS INSURANCE, SALES TAX.

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE PLEASE PAY THIS AMOUNT

CUSTOMER #: 32998

702623



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400

PAGE 3

www.kunibmw.com

SERVICE ADVISOR: 3042863 DAVID STOUT

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG	
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		19373/19375	TP151	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	16:00 06AUG19			CASH	06AUG19
R.O. OPENED:	READY	OPTIONS: SOLD-STK:PHV786537A DLR:36021					
16:56 05AUG19		15:13 06AUG19	ENG:3.0L DOHC Turbo				
LINE OPCODE		TECH	TYPE	HOURS	LIST	NET	TOTAL
END MILES		COMPONENTS					

CUSTOMER REQUESTED A LOANER
CREATED 2019-08-01 04:38:00PM
TAKEN BY DAVID STOUT

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this Invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW
UNLESS OTHERWISE
INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
PLEASE PAY THIS AMOUNT	0.00

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 32998

727765



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 1

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		24717/24718	TG474	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	WAIT 05AUG20			CASH	05AUG20
R.O. OPENED	READY	OPTIONS: SOLD-STK:PHV786537A DLR:36021					
12:42 05AUG20	14:32 05AUG20	ENG:3.0L DOHC Turbo					
		TRN:2MK M DOUBLE-CLUTCH TRANSMISSION					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A OIL CHANGE DUE PE CBS.
06RLUBRICATION.
3047112 CB
1 83-19-2-221-702 BMW WINDSHIELD WASHER
PARTS: 83-19-2-221-702 BMW WINDSHIELD WASHER 3.68
SW1511R42W7L854-445 SET5 OIL-FILTER 14.05
TOELEMENT7144010
037383-2172-449-994 BMW GROUP LL-01 FE
030W-3048325
PARTS: 83-136 LABOR: 58.59 OTHER: 0.00 TOTAL LINE 116.63
24718 0.40 PERFORMED ENGINE OIL SERVICE
ACH-17**BMW***** 24717/24718 TG474

B MULTIF POINTS INSPECTION
02BMZ MPI
5 03047112 INSP
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE 0.00
24718 0.30 TECH PERFORMED COURTESY VISUAL MULTI-POINT AND TIRE
SAFETY-INSPECTION, RESET (ALL 4) TIRE PRESSURES TO SPECIFICATIONS.
PCOD 1234***** 24717/24718 TG474

C MICROFILTER DUE PER CBS.
16 A/C AND HEATER
3047112 CB
1 64-11-9-237-555 MICROFILTER/ACTIVATED
CARBON 643020
PARTS: 64-637 LABOR: 126.00 OTHER: 0.00 TOTAL LINE 126.00
24718 0.70 Replaced micro filter
3047112 CB
1 64-11-9-237-555 MICROFILTER/ACTIVATED
CARBON 643020

D CUSTOMER APPROVES INTERIOR VEHICLE SANITATION VIA AIRBORNE MISTING
PROCEDURE
YES CUSTOMER APPROVES INTERIOR VEHICLE SANITATION
VIA AIRBORNE MISTING PROCEDURE
3047112 CB
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE 0.00

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE SECTION.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	126.00
LESS INSURANCE	
SALES TAX/CAT TAX SURCHARGE	54.63
PLEASE PAY THIS AMOUNT	180.63

DATE: _____ CUSTOMER SIGNATURE: _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE: _____

Customer #: 32998

727765



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
 P.O. Box 4810, Beaverton, OR 97076
 (503) 748-5400
 www.kunibmw.com

PAGE 2

SERVICE ADVISOR: 3042869 DANIEL DALLEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
LONGBRACH	17	BMW M2	WBS1H9C53HV786537		24717/24718	TG474	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16	19AUG16	29SEP2020	WAIT: 05AUG20			CASH	05AUG20
R.O. OPENED		READY	OPTIONS	SOLD-STK: PHV786537A DLR: 36021			
12:42 05AUG20		14:32 05AUG20	ENG: 3.0L DOHC Turbo	TRN: 2MK M DOUBLE-CLUTCH TRANSMISSION			
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
EST: 393.58				05AUG20 12:42	SA: 3042869		
CONTACT: 32998							

CUSTOMER PAY ENVY DISPOSAL FEE FOR REPAIR ORDER

COMPANY NAME: BMW MAINTENANCE
 COMPANY PHONE: [REDACTED]
 POLICY NUMBER: TBD
 POLICY TERM: 36
 EFFECTIVE DATE: 26 JAN 2018
 DEDUCTIBLE: 8.00
 MILEAGE LIMITED DATE: [REDACTED]
 BEGIN MILES: 9655
 END MILES: [REDACTED]
 COMPONENTS: [REDACTED]

WAIT WEB CREATED: 2020-08-04
 08:34 AM TAKEN BY [REDACTED]

Beaverton, OR 97005-1818
 Beaverton, OR 97076
 (503) 748-5400
 www.kunibmw.com
 DANIEL DALLEY

MILEAGE IN / OUT	TAG
24717/24718	TG474
MENT	INV. DATE
	05AUG20
NET	TOTAL

Beaverton, OR 97005-1818
 Beaverton, OR 97076
 (503) 748-5400
 www.kunibmw.com
 DANIEL DALLEY


WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE

By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	184.59
PARTS AMOUNT	145.99
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	3.00
TOTAL CHARGES	333.58
LESS INSURANCE	0.00
SALES TAX/CAT TAX SURCHARGE	0.00
PLEASE PAY THIS AMOUNT	333.58

DATE: _____ CUSTOMER SIGNATURE: _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE: _____



MULTI-POINT INSPECTION VEHICLE HEALTH REPORT



RO# 727765

8/5/2020

Advisor:
Dan Dailey
dan.dailey@kunibmw.com
(971)233-3783

Appointment Scheduling
Online:
By Phone:
(971)233-3783



Services Performed Today

Description	7/5/2020
OIL CHANGE DUE PE CBS.	
MULTI POINT INSPECTION	
MICRO FILTER DUE PER CBS.	
CUSTOMER APPROVES INTERIOR VEHICLE SANITATION VIA AIRBORNE MISTING PROCEDURE	

Outstanding Services

Condition	Recommendations	Estimate Price
Mount and balance 4 new tires	Found tire(s) worn below minimum tread depth	\$1,523.48
Perform 4-Wheel Alignment		\$239.95
Total		\$1,763.43

Contact your advisor at (971)233-3783 to schedule your appointment for Outstanding Services.

Additional Observations

Tire pressure (PSI) set
Front 35 psi

and 1g Service
Front in psi

26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

Rear 35 psi Found tire(s) worn below minimum tread depth

Rear in psi

26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

Measure Front Brake Pads

Front Pad Thickness (mm) in mm

0	1	2	3	4	5	6	7	8	9	10	11	12
---	---	---	---	---	---	---	---	---	---	----	----	----

Measure Rear Brake Pads

Rear Pad Thickness (mm) in mm

0	1	2	3	4	5	6	7	8	9	10
---	---	---	---	---	---	---	---	---	---	----

Check Tread Depth on All Tires

Front Left (mm) in mm

0	0.5	1	1.5	2	2.5	3	3.5	4	4.5	5	5.5	6	6.5	7	7.5	8
---	-----	---	-----	---	-----	---	-----	---	-----	---	-----	---	-----	---	-----	---

Front Right (mm) in mm

0	0.5	1	1.5	2	2.5	3	3.5	4	4.5	5	5.5	6	6.5	7	7.5	8
---	-----	---	-----	---	-----	---	-----	---	-----	---	-----	---	-----	---	-----	---

Rear Left (mm) in mm

10 1.5 2 2.5 3 3.5 4 5 5.5 6 6.5 7 7.5 8

Rear Right (mm) in mm

0 0.5 1 1.5 2 2.5 3 4 4.5 5 5.5 6 6.5 7 7.5 8

meas. Rear Brake Pad Thick. 1.7 1 mm

meas. Front Brake Pad Thick. 1.7 1 mm

PASSED ITEMS

- ⑦ Inspect Battery Depth
- ⑦ Inspect Transmission
- ⑦ Measure Rear Brake Pads
- ⑦ Measure Front Brake Pads
- ⑦ Inspect Fog Light Operation
- ⑦ Inspect Windshield Washer Fluid
- ⑦ Inspect Tires and Wheels Condition
- ⑦ Inspect Power Locking System Operations
- ⑦ Inspect Windshield for cracks, chips and pitting

⑦ Entire exhaust system (condition, leaks, damage, noise), catalytic converter and converter shield/mission

Measure Rear Brake Pads

Measure Front Brake Pads

Inspect Fog Light Operation

Inspect Windshield Washer Fluid

Inspect Tires and Wheels Condition

Inspect Power Locking System Operations

Inspect Windshield for cracks, chips and pitting

Inspect Headlights

Inspect Cooling System

Tire pressure (PSI) set

Check for Maintenance Due

Inspect Fuel Injection System

Inspect Wiper and Washer System

Drive belts (cracks / damage / wear)

Instrument panel / warning indicator lights

Inspect axles, driveshaft(s), U-joints and CV joints/boots

Inspect Brake Lights

Inspect Back-Up Lights

Check Horn Functionality

Inspect Steering Components

Inspect Hazard Warning Lights

Inspect Brake System Components

Inspect engine oil level and condition

Suspension (damage / leaks / worn components)

Inspect Taillight, Turn Signal, Side Marker, and License Plate Lights

- ⑦ Inspect Head Lights
- ⑦ Inspect Cooling System
- ⑦ Tire pressure (PSI) set
- ⑦ Check for Maintenance Due
- ⑦ Inspect Fuel Injection System
- ⑦ Inspect Wiper and Washer System
- ⑦ Drive belts (cracks / damage / wear)
- ⑦ Instrument panel / warning indicator lights
- ⑦ Inspect axles, driveshaft(s), U-joints and CV joints/boots

Inspect Headlights

Inspect Cooling System

Tire pressure

Check for

Inspect Fuel Injection System

Inspect Wiper and Washer System

Drive belts

Instrument panel

Inspect axles

U-joints and

CV joints/boots

Inspect Brake Lights

Inspect Back-Up Lights

Check Horn

Inspect Steering

Inspect Hazard

Warning Lights

Inspect Brake

System

Inspect engine

oil level and

condition

Suspension

(damage /

leaks /

worn

components)

Inspect

Taillight,

Turn Signal,

Side Marker,

- ⑦ Inspect Brake Lights
- ⑦ Inspect Back-Up Lights
- ⑦ Check Horn Functionality
- ⑦ Inspect Steering Components
- ⑦ Inspect Hazard Warning Lights
- ⑦ Inspect Brake System Components
- ⑦ Inspect engine oil level and condition
- ⑦ Suspension (damage / leaks / worn components)
- ⑦ Inspect Taillight, Turn Signal, Side Marker, and License Plate Lights

Inspect Brake Lights

Inspect Back-Up Lights

Check Horn

Inspect Steering

Inspect Hazard

Warning

Inspect Brake

System

Inspect engine

oil level and

condition

Suspension

(damage /

leaks /

worn

components)

Inspect

Taillight,

Turn

Signal,

Side

Marker,

and

License

Plate

Lights

Kuni BMW

10999 SW CANYON RD
Beaverton Oregon 97005

503-748-5400

Customer information

Street: 15410 SW SPARROW LOOP UNIT

Zip code: 970079291

Cardholder Signature

BRIAN IRISH

IRISH

Transaction information

MOTO

Date: 08/05/2020 2:42 PM
 Merchant ID: 12720433
 Terminal ... 00000001
 Invoice No.: 727765_KBMW-S_2020-08-05_1
 Amount: \$333.58
 Card Number: *****8714
 Response M... Approved
 Auth Code: 06871D
 Auth Mode: Issuer
 Processed as: VISA
 Entry Method: Manual
 Trace No.: 001356722050
 Reference No.: 1356722050
 Match AVS: Match Y
 Match ZIP: Match Y
 Match C... Match M
 Client ID: 7e4a349d29efd81845e82f7a4338926b
 Token ID: LQEK2JXL
 User ID: dd10_dms

I Agree to Pay Above Total Amount According to Card Issuer Agreement (Merchant Agreement if Credit Voucher).

Merchant / Customer Copy

CUSTOMER #: 32998

752791



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 1

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
LONGBRACH	17	BMW M2	WBS1H9C53HV786537		29367/29378	TG1112

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	17:00 07SEP21		195.00	CASH	08SEP21

R/O OPENED	READY	OPTIONS: SOLD-STK:PHV786537A DLR:36021
11:56 07SEP21	14:25 08SEP21	ENG:3.0L DOHC Turbo
		TRN:2MK M DOUBLE-CLUTCH TRANSMISSION

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	OIL						
CAUSE: Oil service due							
06 LUBRICATION							
						53.24	53.24
							68.95
							14.05
							3.71
PARTS: 86.71 LABOR: 53.24 OTHER: 0.00						TOTAL LINE A: 139.95	

Oil service due 0.40 Performed oil/filter service

B SERVICE THE REAR DIFFERENTIAL.							
CAUSE: Rear differential service due							
						97.50	97.50
							40.30
							37.70
PARTS: 78.00 LABOR: 97.50 OTHER: 0.00						TOTAL LINE B: 175.50	

Rear differential service due 0.50 Performed rear differential service

C BRAKE FLUID DUE PER CBS							
CAUSE: Brake flush due							
						180.96	180.96
							14.04
PARTS: 14.04 LABOR: 180.96 OTHER: 0.00						TOTAL LINE C: 195.00	

Brake flush due 1.00 Performed brake flush

D MULTI POINT INSPECTION							
CAUSE: Courtesy inspection							

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS OIL LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX/CAT TAX SURCHARGE	

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT
------	--------------------	--	------------------------

CUSTOMER #: 32998

752791



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 2

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
LONGBRACH	17	BMW M2	WBS1H9C53HV786537		29367/29378	TG1112

DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT	INV DATE
30SEP16 IS							
30SEP16	19AUG16	29SEP2020	17:00 07SEP21		195.00	CASH	08SEP21

R.O. OPENED	READY	OPTIONS	SOLD-STK:PHV786537A DLR:36021				
		ENG:3.0L DOHC Turbo					
11:56 07SEP21	14:25 08SEP21	TRN:2MK M DOUBLE-CLUTCH TRANSMISSION					
LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

02BMZ mpi
3043215 INSP
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: (N/C) 0.00
29373 Courtesy inspection 0.30 TECH PERFORMED COURTESY VISUAL
MULTI-POINT AND TIRE SAFETY INSPECTION. RESET (ALL 4) TIRE PRESSURES TO
SPECIFICATIONS.

E CUSTOMER APPROVES INTERIOR VEHICLE SANITATION VIA AIRBORNE MISTING PROCEDURE

YES CUSTOMER APPROVES INTERIOR VEHICLE SANITATION VIA AIRBORNE MISTING PROCEDURE

3043215 IPS (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

F GUEST STATES THERES A ABNORMAL NOISE FROM THE ENGINE AREA, WHEN ACELLERATING ON LOWER RPMs AND GOES AWAY AFTER 3500 RPMs. SOUNDS LIKE A SWOOSHING TYPE SOUND. I/A

CAUSE: Turbocharger boost noise
21 ENGINE

3043215 CB 97.50 97.50
PARTS: 0.00 LABOR: 97.50 OTHER: 0.00 TOTAL LINE F: 97.50
29373 Turbocharger boost noise 0.50 Test drove vehicle, verified whooshing type noise in lower RPMs under load. Noted aftermarket piggy back tuner present and cutout in air box. Covered cutout in airbox, noise reduced. No abnormal noises present, whooshing noise from turbocharger building boost.

G** ALL TIRES ARE WORN OUT. MOUNT AND BALANCE FOUR Michelin PILOT SUPER SPORT FRONT: 245/35ZR19 93(Y) PN#36-11-2-446-275 AND REAR: 265/35ZR19 98(Y) PN#36-11-2-446-276

25 WHEEL AND TIRE
3042306 CB 130.00 130.00
2 36-11-2-446-275 MICHELIN PILOT SUPER SPORT
B:369041 632.22

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED


DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX/CAT TAX SURCHARGE	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

PLEASE PAY THIS AMOUNT

CUSTOMER #: 32998

752791



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 3

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	17	BMW M2	WBS1H9C53HV786537		29367/29378	TG1112

DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT	INV DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	17:00	07SEP21	195.00	CASH	08SEP21

R.O. OPENED READY OPTIONS: SOLD-STK:PHV786537A DLR:36021
 ENG:3.0L DOHC Turbo
 11:56 07SEP21 14:25 08SEP21 TRN:2MK M DOUBLE-CLUTCH TRANSMISSION

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
2	36-11-2-446-276			MICHELIN PILOT SUPER SPORT			774.90
				B:369041			

PARTS: 1407.12 LABOR: 130.00 OTHER: 0.00 TOTAL LINE G: 1537.12
 29373 2.00 MOUNTED AND BALANCED 4 NEW TIRES. SET ALL TIRE PRESSURES
 TO SPEC AND INITIALIZED TPM SYSTEM. NO WHEEL LOCKS.,

H** DOT NUMBER
 25 WHEEL AND TIRE
 3042306 IPS (N/C)
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H: 0.00
 29373

DOT 6U0W 00HX 2420
 DOT 6U0W 00HX 3019
 DOT 6UK3 00HX 5120
 DOT 6UK3 00HX 4920

I** ALIGNMENT-WHEEL
 CAUSE: Alignment due with tires
 18 ALIGNMENT-WHEEL
 3043215 CB 239.95 239.95
 PARTS: 0.00 LABOR: 239.95 OTHER: 0.00 TOTAL LINE I: 239.95
 29378 Alignment due with tires 2.50 PERFORMED 4 WHEEL ALIGNMENT TO
 FACTORY SPECS

EST: 2,610.90 07SEP21 15:58 SA: 3042869
 CONTACT: BRLAN (503) 407-0212
 MAB 4 TIRES AND ALIGNMENT,

CUSTOMER PAY ENV DISPOSAL FEE FOR REPAIR ORDER 3.00


COMPANY NAME BMW MAINTENANCE
 COMPANY PHONE

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED	DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS OIL LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES *	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX/CAT TAX SURCHARGE	
		PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 32998

752791



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com


PAGE 4

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG	
LONGBRACH	17	BMW M2	WBS1H9C53HV786537		29367/29378	TG1112	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	17:00 07SEP21		195.00	CASH	08SEP21
R/O OPENED	READY	OPTIONS: SOLD-STK:PHV786537A DLR:36021					
11:56 07SEP21	14:25 08SEP21	ENG:3.0L DOHC Turbo					
		TRN:2MK M DOUBLE-CLUTCH TRANSMISSION					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
POLICY NUMBER TED INS3							
POLICY TERM 36							
EFFECTIVE DATE 26 JAN 2018							
DEDUCTIBLE 0.00							
MILEAGE LIMIT							
BEGIN MILES 9655							
END MILES							
COMPONENTS							

CUSTOMER REQUESTED A LOANER
WEB CREATED 2021-08 -24
01:02:57PM TAKEN BY



WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	DESCRIPTION	TOTALS
		LABOR AMOUNT	799.15
		PARTS AMOUNT	1585.87
		GAS, OIL, LUBE	0.00
		SUBLET AMOUNT	0.00
		MISC. CHARGES *	3.00
		TOTAL CHARGES	2388.02
		LESS INSURANCE	0.00
		SALES TAX/CAT TAX SURCHARGE	0.00
		DATE	CUSTOMER SIGNATURE
			2388.02



MULTI-POINT INSPECTION VEHICLE HEALTH REPORT



RO# 752791

9/8/2021

Prepared for:
BRIAN IRISH
2017 BMW M2 Base
WBS1H9C53HV786537
29,367 miles

Advisor:
Dan Dailey
dan.dailey@kunibmw.com
(971)233-3783

RO# 752791

9/8/2021

Prepared for:
BRIAN IRISH
2017 BMW M2 Base
WBS1H9C53HV786537
29,367 miles

Advisor:
Dan Dailey
dan.dailey@kunibmw.com
(971)233-3783

Appointment Scheduling
Online:
By Phone:
(971)233-3783

Services Performed Today

	Description
⑦	Mount and balance 4 new tires Found tire(s) worn below minimum tread depth
⑦	Perform 4-Wheel Alignment Found tire(s) worn below minimum tread depth
⑦	OIL ,CHANGE DUE PER CBS
⑦	SERVICE THE REAR DIFFERENTIAL.
⑦	BRAKE FLUID DUE PER CBS
⑦	MULTI POINT INSPECTION
⑦	CUSTOMER APPROVES INTERIOR VEHICLE SANITATION VIA AIRBORNE MISTING PROCEDURE
⑦	GUEST STATES THERES A ABNORMAL NOISE FROM THE ENGINE AREA, WHEN ACELLERATING ON LOWER RPMS AND GOES AWAY AFTER 3500 RPMS. SOUNDS LIKE A SWOOSHING TYPE SOUND.I/A

Additional Observations

Tire pressure (PSI) set

Front

35 psi

Front in psi

26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

Rear

35 psi

Rear in psi

26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

Measure Front Brake Pads

Front Pad Thickness (mm) in mm

0 1 2 3 4 5 6 7 8 9 10 11 12

Measure Rear Brake Pads

Rear Pad Thickness (mm) in mm

0 1 2 3 4 5 6 7 8 9 10

Check Tread Depth on All Tires

Front Left (mm) in mm

0 .5 1 1.5 2 2.5 3 3.5 4 4.5 5 5.5 6 6.5 7 7.5 8

Front Right (mm) in mm

0 .5 1 1.5 2 2.5 3 3.5 4 4.5 5 5.5 6 6.5 7 7.5 8

Rear Left (mm) In mm

0 .5 1 1.5 2 2.5 3 3.5 4 4.5 5 5.5 6 6.5 7 7.5 8

Rear Right (mm) in mm

0 .5 1 1.5 2 2.5 3 3.5 4 4.5 5 5.5 6 6.5 7 7.5 8

PASSED ITEMS

- ☑ Inspect Battery
- ☑ Inspect Transmission
- ☑ Tire pressure (PSI) set
- ☑ Inspect Fog Light Operation

- ☑ Inspect Hazard Warning Lights
- ☑ Inspect Windshield Washer Fluid
- ☑ Inspect Power Locking System Operation
- ☑ Suspension (damage / leaks / worn components)
- ☑ Inspect Taillight, Turn Signal, Side Marker, and License Plate Lights

- ☑ Inspect Head Lights
- ☑ Inspect Back-Up Lights
- ☑ Check Horn Functionality
- ☑ Inspect Steering Components
- ☑ Inspect Brake System Components
- ☑ Inspect Tires and Wheels Condition
- ☑ Inspect engine oil level and condition
- ☑ Inspect Windshield for cracks, chips and pitting
- ☑ Entire exhaust system (condition, leaks, damage, noise, catalytic converter and converter shield)

- ☑ Inspect Brake Lights
- ☑ Inspect Cooling System
- ☑ Check for Maintenance Due
- ☑ Inspect Fuel Injection System
- ☑ Inspect Wiper and Washer System
- ☑ Drive belts (cracks / damage / wear)
- ☑ Instrument panel / warning indicator lights
- ☑ Inspect axles, driveshaft(s), U-joints and CV joints/boots

Kuni BMW

10999 SW CANYON RD

Beaverton Oregon 97005

503-748-5400

Customer information

Street:

15410 SW SPARROW LOOP UNI

Zip Code: 970079291

BRIAN IRISH

Transaction information

RepeatSale

Date: 9/8/2021, 11:58:41 AM

Amount: \$2388.02

Card Number: *****8714

Merchant ID: 12720433

Terminal ID: 00000001

Auth Code: 04730D

Processed as: Visa

Reference No: 1843542189

Trace No: 001843542189

Invoice No:

752791_KBMW-S_2021-09-07_1

Response Msg: Approved

Entry Method: Manual

Match AVS: Match (Y)

Match CV: Not Match (X)

Match ZIP: Match (Y)

Client ID:

7e4a349d29efd81845e82f7a4338926b41fe046b

Token ID: LQEK2JXL

User ID: adpebpadmin

I Agree to Pay Above Total Amount According to Card Issuer Agreement (Merchant Agreement if Credit Voucher).

Loading measurement

Date: 8.9.21 13:37

WinAlign Version 16.3	Specification Version BMW/Univ 120.0.3	Version Hx421 7.1	Cal Date 22.1.20
--------------------------	---	----------------------	---------------------

Customer:	Work Order Position:
Vehicle Key no:	Odometer:29373
Customer number:973	First Reg.:
License:	Technician:

Vehicle BMW : 2 Series M2 - F87 (2015 -) : Series (19" Wheel)

Tire Inspection	Front left	Front right	Rear left	Rear right
-----------------	------------	-------------	-----------	------------

Tire Air Pressure

Tire Tread Depth

Tire Marking	Star	No	No	No	No
--------------	------	----	----	----	----

Rear Axle		Initial Measurement	Target Data	Final Measurement
-----------	--	---------------------	-------------	-------------------

Ride Height	left	619mm	-20mm[615mm]+40mm	619mm
	right	615mm		618mm

Front Axle		Initial Measurement	Target Data	Final Measurement
------------	--	---------------------	-------------	-------------------

Ride Height	left	622mm	-20mm[612mm]+40mm	622mm
	right	621mm		621mm

Rear Axle		Initial Measurement	Target Data	Final Measurement	Target Data
-----------	--	---------------------	-------------	-------------------	-------------

Camber	left	-1°49'	-0°20'[-1°49']+0°20'	-1°48'	-0°20'[-1°48']+0°20'
	right	-1°47'	-0°20'[-1°45']+0°20'	-1°48'	-0°20'[-1°46']+0°20'

Toe	left	0°01'		0°08'	
	right	0°10'		0°08'	
	total	0°12'	-0°12'[0°16']+0°12'	0°16'	-0°12'[0°16']+0°12'

Thrust Angle	total	-0°04'	-0°10'[0°00']+0°10'	0°00'	-0°10'[0°00']+0°10'
--------------	-------	--------	---------------------	-------	---------------------

Front Axle		Initial Measurement	Target Data	Final Measurement	Target Data
------------	--	---------------------	-------------	-------------------	-------------

Camber	left	-1°11'	-0°30'[-1°21']+0°30'	-1°14'	-0°30'[-1°20']+0°30'
	right	-1°13'	-0°30'[-1°19']+0°30'	-1°12'	-0°30'[-1°21']+0°30'
	cross	0°02'	-0°30'[0°00']+0°30'	-0°02'	-0°30'[0°00']+0°30'

Toe	left	-0°01'		0°04'	
	right	-0°01'		0°04'	
	cross	0°00'	-0°12'[0°00']+0°12'	0°00'	-0°12'[0°00']+0°12'
	total	< -0°03' >	-0°12'[0°11']+0°12'	0°09'	-0°12'[0°11']+0°12'

Track differential angle	left	-2°17'		-2°17'	
	right	-2°16'		-2°16'	

Max steering lock on curve inside wheel	left		[-40°00']	
	right			

Caster	left	7°25'		7°25'
	right	7°24'		7°24'

SAI	left	13°54'		13°56'
	right	14°00'		13°59'

Setback	total	-0°08'	-0°15'[0°00']+0°15'	-0°08'	-0°15'[0°00']+0°15'
---------	-------	--------	---------------------	--------	---------------------

<> = Measured value is outside of tolerance

CUSTOMER #: B32998

775646



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400

PAGE 1

www.kunibmw.com

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG	
LONGBRACH-	17	BMW M2	WBS1H9C53HV786537		31989/31990	TG7633	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	18:00 22SEP22		210.00	CASH	22SEP22
R.O. OPENED	READY	OPTIONS: SOLD-STK:PHV786537A DLR:36021					

08:20 22SEP22	13:02 22SEP22	TRN:2MK M DOUBLE-CLUTCH TRANSMISSION				
LINE OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL

A THE CUSTOMER REQUESTS A BMW EXTENDED SERVICE CONTRACT - UC OIL 36 MO/UNL MLS
 ESC THE CUSTOMER REQUESTS A BMW EXTENDED SERVICE CONTRACT.
 3043205 CB 199.00 199.00
 PARTS: 0.00 LABOR: 199.00 OTHER: 0.00 TOTAL LINE A: 199.00

B COURTESY INSPECTION
 CAUSE: PERFORM MPI INSPECTION
 02BMZ COURTESY INSPECTION
 3043205 IMPI (N/C)
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00
 31990 0.30 TECH PERFORMED COURTESY VISUAL MULTI-POINT AND TIRE SAFETY INSPECTION. RESET (ALL 4) TIRE PRESSURES TO SPECIFICATIONS.

C BMW MPU oil only program
 CAUSE: regular service.
 0000252 LOW MILE OIL SERVICE (N/C)
 3043205 WBM (N/C)
 65 83-21-5-A42-D39 BMW GROUP LL01FE (N/C)
 0W-30:832511 (N/C)
 1 11-42-7-854-445 SET OIL-FILTER. (N/C)
 ELEMENT:114010
 FC: 85800388MP
 PART#: _____
 COUNT: _____
 CLAIM TYPE: _____
 AUTH CODE: _____

D AIR FILTER DUE
 CAUSE: regular service.
 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00
 31990 regular service. completed oil service. reset light.

PAID

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX/CAT TAX SURCHARGE	

DATE _____ CUSTOMER SIGNATURE _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

PLEASE PAY THIS AMOUNT

CUSTOMER #: B32998

775646



INVOICE

10999 SW Canyon Rd., Beaverton, OR 97005-1818
P.O. Box 4810, Beaverton, OR 97076
(503) 748-5400
www.kunibmw.com

PAGE 2

SERVICE ADVISOR: 3042869 DANIEL DAILEY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	17	BMW M2	WBS1H9C53HV786537		31989/31990	TG7633

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO. NO.	RATE	PAYMENT	INV. DATE
30SEP16 IS							
30SEP16 DD	19AUG16	29SEP2020	18:00 22SEP22		210.00	CASH	22SEP22

R.O. OPENED: 08:20 22SEP22
 READY: 13:02 22SEP22
 OPTIONS: SOLD-STK:PHV786537A DLR:36021
 ENG:3.0L DOHC Turbo
 TRN:2MK M DOUBLE-CLUTCH TRANSMISSION

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

01 MENU SERVICES
 3043205 CB 147.00 147.00
 1 13-71-7-602-643 AIR FILTER ELEMENT:137012 48.04
 PARTS: 48.04 LABOR: 147.00 OTHER: 0.00 TOTAL LINE D: 195.04
 31990 regular service. 0.70 replaced intake air filter.

E SPARK PLUGS DUE
 CAUSE: regular service.
 04 IGNITIONS SYSTEMS
 3043205 CB 567.00 567.00
 6 12-12-0-039-634 SPARK PLUG, HIGH
 POWER:121031 214.86
 PARTS: 214.86 LABOR: 567.00 OTHER: 0.00 TOTAL LINE E: 781.86
 31990 regular service. 2.70 removed and replaced all spark
 plugs.test drove all ok.


F MICRO FILTER DUE
 CAUSE: regular service.
 16 A/C AND HEATER
 3043205 CB 147.00 147.00
 1 64-11-9-237-555 MICROFILTER/ACTIVATED
 CARBON:643010 64.71
 PARTS: 64.71 LABOR: 147.00 OTHER: 0.00 TOTAL LINE F: 211.71
 31990 regular service. 0.70 replaced micro filter.

G VEHICLE CHECK DUE
 CAUSE: regular service.
 01 MENU SERVICES
 3043205 CB 165.00 165.00
 PARTS: 0.00 LABOR: 165.00 OTHER: 0.00 TOTAL LINE G: 165.00
 31990 regular service. 0.80 completed vehicle check service. reset
 light

WARRANTY STATEMENT AND DISCLAIMER: PLEASE SEE THE DEALERSHIP'S LIMITED WARRANTY ON THE REVERSE SIDE OF THIS REPAIR INVOICE. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED	DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES *	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX/CAT TAX SURCHARGE	
		PLEASE PAY THIS AMOUNT	

DATE: _____ CUSTOMER SIGNATURE: _____ AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE: _____

Multi-Point Inspection Summary



Thursday, September 22, 2022 11:40 AM

RO# 775646

VIN : WBS1H9C53HV786537

CUSTOMER INFORMATION

Brian Irish

B.IRISH@COMCAST.NET

+15034070212, +15033144877,

+15034070212, +15033144877

CAR INFORMATION

BMW

M2

31989

SERVICE ADVISOR INFO








Dan Dailey

TECHNICIAN

Nick Hammond

ORIGINAL CUSTOMER REQUESTS

OTHER

	THE CUSTOMER REQUESTS A BMW EXTENDED SERVICE CONTRACT.- UC OIL 36 MO/UNL MLS	Total Approved: \$0.00 Original Approved: \$0.00
	COURTESY INSPECTION	Total Approved: \$0.00 Original Approved: \$0.00
	BMW MPU oil only program	Total Approved: \$0.00 Original Approved: \$0.00
	AIR FILTER DUE	Total Approved: \$0.00 Original Approved: \$0.00
	SPARK PLUGS DUE	Total Approved: \$0.00 Original Approved: \$0.00
	MICRO FILTER DUE	Total Approved: \$0.00 Original Approved: \$0.00
	VEHICLE CHECK DUE	Total Approved: \$0.00 Original Approved: \$0.00

1 Needs Attention Soon

CUSTOM RECOMMENDATION

Custom Recommendation	Repair Estimate: \$627.44
aged battery installed. replace and register battery	

29 Passed Inspection

LIGHTS

- Inspect Head Lights
- Inspect Fog Light Operation
- Inspect Brake Lights
- Inspect BackUp Lights
- Inspect Hazard Warning Lights
- Inspect Taillight, Turn Signal, Side Marker, and License Plate Lights

BATTERY

- Inspect 12 Volt Battery

UNDER HOOD: FLUIDS AND FILTERS

- Inspect Engine Oil Level and Condition
- Inspect Cooling System
- Inspect Windshield Washer Fluid Filled as needed - Filled
- Drive belts (cracks / damage / wear)
- Inspect Fuel Injection System

TIRES AND ALIGNMENT

- Check Tread Depth on All Tires
 - Front Left - 7mm
 - Front Right - 7mm
 - Rear Left - 6.5mm
 - Rear Right - 6.5mm
- Wheels Condition
- Tires Condition

UNDER CAR : SUSPENSION, DRIVELINE, EXHAUST, LEAKS

- Inspect Transmission
- Suspension (damage / leaks / worn components)
- Entire Exhaust System (condition, leaks, damage, noise, catalytic converter and converter shield)
- Steering Components
- Inspect Axles, Driveshaft(s), U-joints and CV joints/boots

GENERAL MAINTENANCE

- Inspect Wiper and Washer System
- Check Horn Functionality

OTHER

- Check for Maintenance Due
- Instrument Panel and Warning Indicator Lights
- Inspect Power Locking System Operation

BODY/GLASS/TRIM

- Inspect Windshield for cracks, chips and pitting

BRAKES

- Front Brake Pads Measurement Front Pad Thickness - 8mm
- Rear Brake Pads Measurement Rear Pad Thickness - 8mm
- Brake System Components

OTHER COMMENTS

Tire Pressure

Front Tires - 35PSI

Rear Tires - 35PSI

Original Customer Requests

original approved subtotal: \$0.00

Recommendation approved subtotal: \$0.00

Taxes: \$0.00

Total Approximate Cost of Visit: \$0.00

Prices guaranteed for 30 days, except tires.

X

SIGNATURE

DATE



BMW Parts Hub



Order # 4204

Record #3387145

Created at: February 21st 2019, 4:05:07 pm

Last status change: March 1st 2019, 8:21:27 am

BMW Parts Hub
 Otto's BMW
 1275 WILMINGTON PIKE
 WEST CHESTER, Pennsylvania 19382
 United States
PHONE: (855) 269-1880
EMAIL: support@bmwpartshub.com
WEBSITE: https://www.bmwpartshub.com

Product ID	Product Name	Price	Quantity	Total
62-10-8-097-793	Instrument Cluster 621010	\$1,167.56	1	\$1,167.56
			Subtotal :	\$1,167.56
			Promo Discount : PROMO CODE: SALES	-\$3.26
			Shipping (FedEx Ground) :	\$65.27
			Total :	\$1,229.57

Payment Information: Visa x-8714



Otto's BMW

1275 Wilmington Pike, West Chester, PA 19382
(610) 399-6800 Fax: (610) 399-4147
Parts Direct: (610) 399-4171 www.ottosbmw.com



SOLD TO	SHIPPED TO
BMWPARTSHUB.COM	

RETURN POLICY: No returns on electrical or special order items. All claims and returned goods must be accompanied by this invoice. A restocking charge will be applied on all merchandise returned for credit. No returns after 30 days.

DISCLAIMER OF WARRANTIES: All warranties on the products sold hereby are those made by the manufacturer. The seller, OTTO'S BMW, hereby expressly disclaims all warranties, either expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose, and OTTO'S BMW, neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

YOUR PURCHASE ORDER		TERMS		INVOICE DATE		INVOICE NUMBER / PG.				
4204		NET DUE 30 DAYS		3/01/19		15015976 1				
SHIP VIA				SALESPERSONS NAME						
WILL CALL				JG						
QTY.	DESCRIPTION	SOURCE	LIST	NET	AMOUNT					
1	Freight Out 62 10 8 097 793 : B1-Instrument c [REDACTED] GERMANY 2-3 WEEKS CUSTOMER IS AWARE	SPORD	1586.58	1167.56	62.01 1167.56					
DATE PRINTED	3/01/19	TIME	8:22:26	SERVICES OR EQUIPMENT			1167.56			
PARTS DEPARTMENT HOURS 8:00 a.m. to 5:00 p.m. Mon - Fri 9:00 a.m. to 4:00 p.m. Sat Thank You!				SHIPPING			62.01			
				C.O.D. CHARGE						
				SALES TAX OR TAX I.D.			xxxxFILE	.00		
				DEPOSIT ON CONTRACT						
				TOTAL						1229.57
				A/RB3000 BMWPARTSHUB.COM			1229.57			
NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.										
X										



Brian,

Thank you for your order. Please call, text, or email as soon as you receive this package to schedule your coding appointment.

What you will need:

1. Fully charged laptop
2. Your vehicle within range of a WiFi hotspot
3. The enclosed USB flash drive (labeled "C")
4. The enclosed ENET cable

How the appointment will work:

1. We will call you at the appointment time and instruct you to insert the USB drive into your laptop and insert the ENET cable into your vehicle and into the laptop.
2. In the USB you will find two folders. Please access the folder for your Operating System and then select the **teamviewer.exe** (Windows) or **teamviewer.dmg** (MacOS). You will need to install TeamViewer on your computer for us to complete the coding session.
3. We will then verify the ID and Password and remote connect to your laptop for the remainder of the process.

If you are satisfied with our services, we encourage you to post a review on the Bimmerfest forums (www.bimmerfest.com). Reviews and referrals are an integral part to our business and we pride ourselves on making sure every customer is satisfied.

If your vehicle needs to be re-coded due to the dealership installing a software update, we will re-code your vehicle at a 50% discount.

Please use the enclosed prepaid envelope to return the USB flash drive and cable. Please drop it off at your nearest USPS location at your convenience.

Thank you.

David Worthley | Coding Specialist
Bimmer America LLC
David@bimmeramerica.com
914-500-8585

Customer Invoice
167746
03/24/2019

FIRESTONE COMPLETE AUTO CARE
TIGARD
13500 SW PACIFIC HWY
TIGARD, OR. 97223-4803

Service Advisor:
01 GREG
503.620.2700

2017 BMW M2 BASE
3.0L L6 FI GAS
Lic #: GW00745 OR Vin #:
In: 03/24/19 9:05AM Mileage: 15,256
Out: 03/24/19 9:11AM

Store # 018945

RETAIL SALE

Description	Rev Hist /Article #	ID	Qty	Unit Price	Extended Price	Job Total
FLAT REPAIR & BALANCE50 SERIES AND BELOW W/TPMS (Rear-Left)		01				39.98
6-138 TPMS KIT 7020K	7010680	30NN	1	7.00	7.00	
FLAT REPAIR - PATCH-PLUG	7020060	30NN	1	1.99	1.99	
TPMS VALVE SERVICE KIT LABOR	7008190	30NN	1	2.99	2.99	
LP FLAT REPAIR LABOR	7008211	30NN	1	21.00	21.00	
FLAT REPAIR BALANCE LABOR	7013645	30NN	1	7.00	7.00	

Technician(s):

30 DEREK

Payment History:

Visa 8714 39.98 00302D Sale
MID: 222220327243
Term: 0002 Card Inserted
AID:A0000000031010 PIN NOT VERIFIED
Total Tendered 39.98

Summary:

Parts	8.99
Labor	30.99
Shop Supplies	0.00
Sub-Total	39.98
Tax (0.00%)	0.00
Total	\$39.98

I have received the above goods and/or services. If this is a credit card purchase, I agree to pay and comply with my cardholder agreement with the issuer.

Customer Signature

All parts are new unless otherwise specified.

HOW ARE WE DOING?

Tell us about your experience today!
Complete a 4-minute survey for a chance to win one of ten \$50 gift cards each month!
Visit www.FirestoneSurvey.com within 4 days and enter Code 018945-167746

www.FirestoneCompleteAutoCare.com



10999 SW Canyon Rd.
 Beaverton, OR 97005-1818
 P.O. Box 4810, Beaverton, OR 97076
 (503) 748-5400
 www.kunibmw.com

RETURN/REFUND POLICY: ALL RETURNS MUST BE ACCOMPANIED BY THIS INVOICE AND ARE SUBJECT TO A RESTOCKING CHARGE. RETURNED ITEMS MUST BE IN THE ORIGINAL UNOPENED BOX OR CONTAINER. PLEASE NOTE THAT THE DEALERSHIP WILL NOT ACCEPT RETURNS OR MAKE REFUNDS AFTER 30 DAYS. NO REFUNDS OR RETURNS ON SPECIAL ORDER PARTS OR ELECTRICAL PARTS.

DISCLAIMER OF WARRANTY: ANY WARRANTIES ON THE PARTS OR PRODUCTS DESCRIBED BELOW ARE THOSE OF THE MANUFACTURER OR SUPPLIER OF THE PARTS OR PRODUCTS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WITH RESPECT TO THE SAME. *THE LIMITED WARRANTY ON THE REVERSE SIDE OF THIS INVOICE APPLIES ONLY TO PARTS INSTALLED AND/OR REPAIRS PERFORMED BY OUR DEALERSHIP.* THE DEALERSHIP NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PARTS OR PRODUCTS. THIS DISCLAIMER IN NO WAY AFFECTS THE PROVISIONS OF ANY MANUFACTURER OR SUPPLIER WARRANTIES.

DATE ENTERED 19 MAR 19	YOUR ORDER NO. 2017 M2	DATE SHIPPED 23 MAR 19	INVOICE DATE 23 MAR 19	INVOICE NUMBER 631972	16:45
---------------------------	---------------------------	---------------------------	---------------------------	--------------------------	-------

S
O
L
D
T
O
 ACCOUNT NO. 32998
 S
H
I
P
T
O
 PAGE 1 OF 1

SHIP VIA CWI	SLSM. 304274	S/L NO.	TERMS CREDIT CARD	F.O.B. POINT BEAVERTON, OR
-----------------	-----------------	---------	----------------------	-------------------------------

QTY	SHIP	P.O.	PART NO.	DESCRIPTION	LIST	NET	AMOUNT
1	1	0	82-11-0-443-851	SPORD SUNSHADE:	65.00	52.00	52.00

PARTS	52.00
SUBLET	
FREIGHT	0.00
SALES TAX	0.00

CUSTOMER'S SIGNATURE

X


TOTAL \$52.00

COVERCRAFT® Installation Instructions

SINCE 1965

www.covercraft.com

UVS100® CUSTOM SUNSCREEN




IMPORTANT NOTICE



UVS100® Custom Sunscreens do not cover the entire glass area on some vehicles. Windshield pillar post size and angle, rearview mirror shape and size, and additional sensors can prevent some Sunscreens from providing total blackout coverage.

STEP 1

Unfold your UVS100® Custom Sunscreen with the reflective side facing outward and place it as flat as possible onto the dash area. If there are assist handles on the windshield pillars, make sure the Sunscreen fits in front of them. Then slide it forward until it reaches the bottom of the windshield ahead of the defroster vents.



STEP 2


With both hands, lift the top of the UVS100® Custom Sunscreen into the windshield area.

NOTE: Be careful to not bend the corners while installing, as damage to the inner insulator may occur.



STEP 3


Pull down each sun visor to hold the UVS100® Custom Sunscreen in place. In some cases, the Sunscreen may not reach all the way to the windshield pillars. This additional space is necessary to be able to install the Sunscreen without damaging it.



REMOVAL

Simply reverse the installation steps, fold the unit and store in the trunk or under a seat.

For more instructions and "How To" videos, visit Covercraft's YouTube Channel: www.youtube.com/covercraft1965



(Optional storage bag shown)

Form # 6317507 (04/17)