

# Multi-Point Inspection Form

RO# 6069092  
 INVENTORY: PNP1696  
 VIN WP0AA2A74KL101696

Advisor Irma Merrow  
 Technician Aaron Ostapenko  
 Created On 1/24/2025

Checked and OK at this time

May Require Future Attention

Requires immediate attention

## Interior / Exterior

- Bulbs and Lights
- Windshield Wipers / Windshield Washer Spray / Wiper Operation / Wiper Blades / Wiper Arms / Including Rear (if applicable)
- Windshield Condition (inspect for Cracks, Chips, or Pitting)
- Upholstery / Carpet / Floor Mats / Mirrors / Glass
- Emergency Brake Adjustment
- Horn Operation
- Fuel Tank Cap Gasket
- Clutch Operation (if equipped)
- Air Conditioning Filter (if equipped)
- Cabin/HEPA Filter (if equipped)
- Engine Air Filter
- Wiper Blades

## Under Vehicle

- Shock Absorbers / Suspension
- Steering Gear Box / Linkage and Boots / Ball Joints / Dust Covers
- Muffler / Exhaust Pipes / Mountings
- Engine Oil and/or Fluid Leaks
- Drive Shaft Boots / Constant Velocity Boots / U-joints / Transmission Linkage (if equipped)
- Transmission / Differential / Transfer Case (Check Fluid Level, Fluid Condition and Fluid Leaks)
- Fuel Lines and Connections / Fuel Tank Band / Fuel Tank Vapor Vent System Hoses
- Inspect Nuts and Bolts on Body Chassis

## Under Hood

- Fluid Levels: Oil / Coolant / Battery / Power Steering / Brake Fluid / Washer
- Engine Air Filter
- Drive Belts (condition and adjustment)
- Engine Coolant Protection
- Cooling System Hoses / Heater Hoses / Air Conditioning Hoses and Connections
- Radiator Core / Air Conditioning Condenser (if equipped)

## Battery Performance

- Battery Terminals / Cables / Mountings
- Check Condition of Battery (Storage Capacity Test if Applicable)

## Tread Depth (measured in 1/32")



- LF Z
- RF Z
- LR Z
- RR Z

## Abnormal Wear Pattern of Tires

- LF
- RF
- LR
- RR

## Check Brake Linings (measured in millimeters)

- LF Z
- RF Z
- LR Z
- RR Z

*- oil change*